









# ULTIMATE SUPPORT®

## Instructions for Assembling 12" Extensions

### Included Parts with the 12" Extensions - BOX 3


	10-16 x .75" Self-Drilling Screw	x4
	1/4 - 20 x 5/8" Pan Head Screw	x8
	Leg Gusset - Left	x1
	Leg Gusset - Right	x1
	12" Extension - Right	x1
	12" Extension - Left	x1

### Additional Parts Needed from other boxes - BOX 1 & 2

	Assembled core table with legs (Instructions for assembling core table and legs are included in box 1 & 2)	x1
	1/4 - 20 x 5/8" Pan Head Screw	x16

# ULTIMATE SUPPORT®

Lay core table with attached legs and 12" side extensions facing down with screw holes facing up. Slide right and left 12" extensions into dowel rods on both sides of core table. Use the 16 remaining screws from the core desk assembly to attach brackets (1/4-20 x 5/8" pan head screw provided in box 1).



Attach left and right gussets to 12" extensions using the four pan head screws for each side. Make sure that gusset's holes line up with leg and 12" extension holes. Attach gussets to legs using the two self-drilling screws for each side.

